	nesday, 13/08/2008 10:55:13 AM SP	1 08 Process	Sheet		Split
Customer Job Number	: CC-DAR01 Dart Aerospace Ltd.	11	awing Name	: GLARESHIELD ASSEMBLY	
	: 41207-74-3	/			
Estimate Number	: 13291	D.	at Normbon	: D3690041	
P.O. Number			rt Number	- D3690 REVB	
This Issue	: 13/08/2008 S.O. No. :		awing Number	: D3090 KEVB	_
Prsht Rev.	: NC		oject Number	D	3
First Issue	***************************************		awing Revision	: B	4
Previous Run	: 41018		aterial	: 01/09/2008	✓ ¥ Um: Eac
Written By	1		ie Date	: 01/09/2008	7 6 011.
Checked & Approv	red By : 300 08-	8.13			/)
Comment		new issue DD verified by:ec revB as per dwg DD verified b			
Additional Product		leve as per any DD vermed b	,,,,,		
ABI	- 4	12			
Job Number:		, <sup>(1)</sup>	2 3	3.5	
Seq. #:	Machine Or Operation:		cription :		1 100
1.0	PACKAGING 1	PACKAGING R	(ESOURCE #1		
Comm	ent: PACKAGING RESOURCE #1	7			
	Pick Packing Kit		ıl.		
2.0	D36901	Glareshield		100000000	
		* 2 Sept.	1		
Comm	ent: Qty.: 1.0000 Each(s)/Unit	Total: 3.0000 Each(s)			. 1
	Glareshield batch: 41222 k	11021	3 406	264 SB	00/09/08
3.0	D3,697041	Tube Assembly			
Commo	ent: Qty.: 1.0000 Each(s)/Unit	Total: 3.0000 Each(s)			1
0.00	Tube Assembly batch: 40665	14/102/02		FF 08	109/00
Comme				FF 08	109/00
4.0	Tube Assembly batch: 40665 @ 1	/ 4/1021© Support Angle		FF 08	109/08
4.0	Tube Assembly batch: 40665	Support Angle  Total: 3:0000 Each(s)		FF 08	109/08 (P10)
4.0	Tube Assembly batch: 40665 © 1	/ 4/1021© Support Angle			109/0d
4.0	Tube Assembly batch: 40665 © 10000 Each(s)/Unit	Support Angle  Total: 3:0000 Each(s)			109/08 09/08
4.0	Tube Assembly batch: 40665 © 100665 © 1	Support Angle  Total: 3:0000 Each(s)			<b>P</b> 70
4.0 Comme	Tube Assembly batch: 40665 © 10000 D36981  ent: Qty.: 1.0000 Each(s)/Unit Support Angle batch: 3 41022	Support Angle  Total: 3:0000 Each(s)			<b>1</b> 070
4.0 Commo	Tube Assembly batch: 40665 © 10000 D36981  ent: Qty.: 1.0000 Each(s)/Unit Support Angle batch: 3 41022	Support Angle  Total: 3:0000 Each(s)  Washer  Total: 18:0000 Each(s)	3416		<b>9</b> 70
4.0 Commo	Tube Assembly batch: 40665 © 100665 © 1	Support Angle  Total: 3:0000 Each(s)  Washer	3416		58/09/03

## Dart Aerospace Ltd

N/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector			
		*					100			
							113			

					QA: N/C	Closed:	_ Date: _	
NCR:41	207-	3 WC	ORK OR	DER NON-CONFORMANC	E (NCR)			
7 - 2	200	Description of NC		Corrective Action Section B		Vigti		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspecto
రశ్రీ అక్ఫుడి	A.	All D3698-1 B41022? B40666 pugles me scrap. 2 D3690-041'su revectorilled to try and in stall the D3698-1. R.C. error on the panels.	//	D3698-1 B41022, And Pull from stock B40666 to surpp.	S3 (3) (3) (3) (3)	krosos	Josian	Posiur
			Posiur	See NCR 08-080.	810/08/28	102.09.03	POSION	1051042
SHOR 05	3	Dependentied.  Lack of Attention.  Open de la et 129  and Prop Rivet (29)  Charge CR 32+3-4-03	#	ACHOTABLE PLENTON	08.09.05		Josians	Ja. 52.0
NOTE: Da	ate & initi	Instead Rivet MS 20 MOAD al all entries	3.2					



Wednesday, 13/08/2008 10:55:13 AM Julie Lecoca

## **Process Sheet**

customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: GLARESHIELD ASSEMBLY

Description:

Job Number: 41207

Job Number:

8.0

9.0

10.0

Part Number: D3690041



Seq. #:

Machine Or Operation: 6.0 MS20426AD34

Comment: Qty .: 2.0000 Each(s)/Unit RIVET

Total:

6.0000 Each(s)

RIVET

3213-4-Rivet, Universal Head

08.09.05 Comment: Qty.: 35.0000 Each(s)/Unit

Total: 105.0000 Each(s)

batch: 1715541 SMALL FAB 1

M16896 - # 08.05.05

SMALL & MEDIUM FAB RESOURCE 1



Rivet, Universal Head

Comment: SMALL & MEDIUM FAB RESOURCE 1

1- transfer drill D3697-041 and D3698-1 in D3690-1 and assemble as per dwg D3690 QC5

INSPECT WORK TO CURRENT STEP 08-09.08

Comment: INSPECT WORK TO CURRENT STEP

PACKAGING 1

Comment: PACKAGING RESOURCE #1

Identify wiith Dart part # and batch # using a fine point permanent marker on inside of part and Stock

Location:

11.0 QC21

FINAL INSPECTION/W/O RELEASE

PACKAGING RESOURCE #1



Comment: FINAL INSPECTION/W/O RELEASE Job Completion

U 38/09/08/

08/09/08

F 08/09/08

391		
•		
	-	
	1	

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
060903	70	MS204#0AD3-5 me required -4's use to start perm change i upotate dug.	1	)/A /			1			
18/व्य/व्य	7.0	replace MS20470AD-34 for cherry river CER274'SS3-4 perm-change a update dug		7/		62 -9-63	16.000			

Part No: <u>D3690-041</u> PAR #: \_\_\_\_ Fault Category: \_\_\_\_ NCR: Yes No DQA: \_\_\_ Date: \_\_\_\_ QA: N/C Closed: \_\_\_ Date: \_\_\_\_

DATE	STEP	Description of NC		Corrective Action Section B	7	The Digital		
		Section A	Initial Chief Eng	Action Description Sign & Date			Approval Chief Eng	Approval QC Inspector
७८५८	80	HOLE MARKED & ON DUG CLAS ENLARGED WHILE REMOVING I BE REWORK ON WO.C.	Ob. agg	REPLACE MS20470.403-5 WITH AS20470 AD4-5 POR THIS W/O ONLY (QTY=1)			38.0203	
& ઈન્૦ઇ	i in the	Also I hole is enlarge Around the vivet. MS 20470 AD 4-5 (above Leck of Attention upon re-new		Remove: Replace enrefully the 03697-041, poll 1x 03697-041 B 1x 03697-041 scrap.			Posicur	10809.0
8.09.06	8.0	hole is enlarged around ix  CCR 274553-4 rivet, e'  Another was chilled and installed through the original MS20470A03-  P.C. Lack of attention i carlegres	-5 JUSTIME	the 03697-041 Qty 1			Pesimi	1000000

**Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES** Perener change PROCEDURE CHANGE Approval Chief Eng / DATE STEP Approva. By Date Qty QC Inspector Prod Mar Spry Pait AS per OST 005 4.2. Flat black usin 1 Cohascult 22. MI 08 09 08 11

Respect Spry Pait QCI4 U 2009 08 8618 9.2 Part No: 03690 -041 PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_ Date: Resolution: Disposition: QA: N/C Closed: Date: NCR:41207-3 WORK ORDER NON-CONFORMANCE (NCR) **Corrective Action** Section B **Description of NC** DATE STEP Verification Approval Approval Initial **Action Description** Section A Sign & Section C Chief Eng QC Inspector Chief Eng Chief Eng. Date NOTE: Date & initial all entries

H-/feodmaio......

10.00				
,				
	ALLER OF THE STATE			